

SITE LOCATION		BILL TO:	
City of Scottsdale, Police Department 7601 East McKellips Road, Scottsdale, AZ 85257 Mr. Allan Kosecki, pkosecki@scottsdaleaz.gov		Full Spectrum	
Service Rep: Joe Galvez		Service Type: Repair	Quality Level: Standard
Billing Type: Non-Billable		Payment Method: Service Contract	PO#: N/A
System ID	Manufacturer	Model	Serial#
GC w/ HS			CN14160045
Additional Instruments			
PROBLEM DESCRIPTION:			
Installation of two new GC analytical columns.			
WORK PERFORMED:			
Powered off instrument and turned off the carrier gas. Removed the existing columns and installed the GC columns, making sure the proper length was introduced into the FID detector side. Injected a test sample, which had FID (A) peaks tailing more than expected. Removed the column from FID (A) and cleaned the FID jet and column adapter of any graphite from ferrules. Reinstalled the column and performed another test injection. Test injection had good chromatography for both FID detectors. System is operating properly.			

Parts Total:

HOURS	RATE	TOTAL	
Labor Hours: 2.0	Labor Rate: \$300	Labor Total:	\$600
Travel Hours: 1.0	Travel Rate: \$300	Travel Total:	\$300
	Extended Travel: \$0	Misc. S&H:	\$0.00
	NOT AN INVOICE, TAXES NOT INCLUDED	Total Labor:	\$900
		Report Total:	\$900.00
~i:72:100~		Credit Amount:	\$900.00
		Balance Due:	\$0.00