## ZONING INTERPRETATION RECORD

Subject of Interpretation: Minimum distance between building on adjacen	it
lots at Sonoran Highlands Phase II (R1-70 Zoning)	
TOUS GC DONOICE TO THE TOUR TOUR TOUR TOUR TOUR TOUR TOUR TOUR	
Zoning Ordinance Section Number: Article V, Section 5.034.F.2. and Amer	ided
Development Standards per Case 2-Z-84	
Standard Distance Between Buil	ldings
Title of Section: Property Development Standards, Distance Between Buil	
Cause for Interpretation: There was an error made in the pre-planning	staces
of this development. Case 2-Z-84 amended the development standards for	
gubdivision. The side yard setback was reduced from thirty (30) feet	
twenty (20) feet. However, the minimum distance between buildings [si	
[60] feet] was not reduced to reflect the new side yard requirements.	It
should have read "a forty (40) foot distance is required between main	
buildings on adjacent lots".	
buildings on adjacent lots.	
Interpretation: The amended development standards for Sonoran Highland	E
Phase II should read, "the minimum distance between main buildings on	
adjacent lots shall not be less than forty (40) feet."	
adjacent Lots shall not be less than toldy (30, 100)	

Interpretation by Thomas J. Rief