

MS4 Name:

Phase I MS4 2021-2022 Annual Report

MS4 Permit #:

1.0	Mic	scellaneous		
1.0	1.	The Permittee shall submit one (1) copy of the most recent SWMP. Please submit the SWMP as an attachment in MS Word/Excel or Adobe PDF.		
	2.	The Permittee shall provide the costs of the necessary capital and operation and maintenance expenditures necessary to accomplish the activities required of the permit.		
		Please submit the O&M Expenditures in MS Word/Excel or Adobe PDF.		
2.0	Lea	gal Authority		
3. Did the Permittee develop, maintain, and enforce adequate		Did the Permittee develop, maintain, and enforce adequate legal authority to control the discharge of pollutants into and from its MS4, per 2.0?		
		Yes No		
		If no, please continue to next question; this requirement is due with the 2023 annual report.		
3.0	Ariz	zona Surface Water Quality Standards (SWQS)		
	4.	How many parameters had SWQS exceedances from discharges to protected surface waters? (Expressed in numbers.)		
4.1	Progi	ram Implementation		
	5.	Did the Permittee include the 4.1.A.1-2 required items in the SWMP?		
		Yes No		
	If no, please explain why (OPTIONAL):			

4.2 Public Education and Outreach

6.	Did the Permittee provide outreach and education to the public on the stormwater
	program issues and requirements, per 4.2.A?

Yes No

Target Group(s):

Topic(s):

If no, please explain why (OPTIONAL):

- 7. Did the Permittee evaluate and measure the understanding and adoption of the targeted behaviors for at least one target audience in at least one subject area by the end of year four (4), per 4.2.A.3?
 - Not applicable for this reporting year.
- 8. Did the Permittee use the results of the evaluation to direct education and outreach resources most effectively, as well as to evaluate changes in adoption of the targeted behaviors by the end of year four (4), per 4.2.A.3?

 Not applicable for this reporting year.
- 9. Attach, as part of your 4th year annual report, an evaluation of the target audience in a subject area and any changes adopted in response to targeted behaviors in order to be more effective, per 4.2.A.3.a.
 - Not applicable for this reporting year.

4.3 Public Involvement and Participation

10. Did the Permittee host an annual public SWMP workshop, per 4.3.A?

Yes No

If no, please explain why (OPTIONAL):

11.	Did the Permittee create opportunities for citizens to participate in the implementation of stormwater controls (e.g., stream clean-ups, storm drain stenciling, volunteer monitoring, disposal of household hazardous waste, educational activities, and facilitation of Adopt-A-Wash, Adopt-A-Park, and Adopt-A-Street litter control activities), per 4.3.B?			
	Yes	No		
	If no, please explain why	(OPTIONAL):		
12.	•	and publicize a reporting system to facilitate and track discharges and/or dumping to the MS4 on a continuous		
	Yes	No		
	If no, please explain why	(OPTIONAL):		
13.	13. Was the current SWMP and annual report posted no later than thirty (30) dathed date of the annual report or, if in the first year of the permit become effective, was the current SWMP and latest annual report posted or Permittee's website, per 4.3.D?			
	Yes	No		
	If no, please explain why	(OPTIONAL):		
Illic	it Discharge Detection ar	nd Elimination (IDDE)		
14.	•	ent a program to detect, investigate, and eliminate non- cluding dumping and spills, into its system, per 4.4.A?		
	Yes	No		
	If no, please explain why	(OPTIONAL):		

4.4

15.	Did the Permittee maintain an inventory of all known MS4 outfalls, field screening points, interconnections with other MS4s, and those major outfalls identified by the Permittee as priority for illicit discharges or other non-stormwater flows, per 4.4.C?							
	Yes		No					
	If no, please ex	plain why (OF	PTIONAL):					
16.	Did the Permit responsibilities	•	J				ct stormw	ater
	Yes		No					
	No nev	v employees v	were hired d	luring the	e reporti	ng year.		
	If no, please ex	plain why (OF	PTIONAL):					
17.	Did the Permit	ee inspect all	l "priority" m	ajor outf	alls or fi	eld screer	ning points	, per
	Yes		No					
	If no, please ex	plain why (Of	PTIONAL):					
18.	Did the Permit screening point 20% each year If no, please ex	ts at least ond) per 4.4.E.3?	ce within the Yes	_		•		
	How many nor numbers):	ı-priority outfa	alls or field s	creenin	g points	were insp	ected (in	

19.	per 4.4.E.4?		
	Yes	No	
	If no, please explain wh	ny (OPTIONAL):	
20.			riate agency with authority to all reports of illicit discharges
	Yes	Ne	
21.		te corrective actions and/or e	
	Yes	Ne	
	If no, please explain w	rhy (OPTIONAL):	
22.	The Permittee shall sub in tabular format.	mit one (1) copy of their 4.4.1.2	2 summary of IDDE activities
	Please submit the Sum	mary of IDDE Activities as ar	n attachment in MS Excel.

4.5	Mur	nicipal Facilities Po	Ilution Prevention	and Good Housekeeping Pr	actices
	23.	Did the Permittee provide new employee training at least (1) one time per year to employees with direct stormwater responsibilities, per 4.5.A.1?			
		Yes	N	0	
		No new e	mployees were hire	ed during the reporting year.	
		If no, please expla	in why (OPTIONAL	.):	
			•	r training for existing employ ce every two (2) years, per 4.7.	•
		Yes	N	0	
		If no, please expla	in why (OPTIONAL	.):	
	24.	equivalent tracking	system of facilities	n an inventory, database, list, m owned and operated by the Pe ints to the MS4, per 4.5.B.1?	•
		Yes	No)	
		If no, please expla	in why (OPTIONAL	_);	
				,	
	25.	The Permittee shal attachment.	l submit one (1) coր	py of their 4.5.B.1 inventory list	as an
		Please submit the	Facilities Owned a	and Operated Inventory List as	an

attachment in MS Excel or Adobe PDF.

26. Did the Permittee inspect approximately 20% of all facilities identified in 4. per 4.5.C.1?			d in 4.5.B.1,	
	Yes	No		
	If no, please explain why	(OPTIONAL):		
27.	·	menting practices, policies, and procedures ociated with runoff from all lands owned and?		
	Yes	No		
	If no, please explain why			
		Sources (Non-municipally owned)		
28.	•	le new employee training at least (1) one time tormwater responsibilities, per 4.6.A.1?	e per year to	
	Yes	No		
	No new employees were hired during the reporting year.			
	If no, please explain why	(OPTIONAL):		
	Did the Permittee provide refresher training for existing employees directly involved in these activities at least once every two (2) years, per 4.7.A?			
	Yes	No		
	If no, please explain why	/ (OPTIONAL):		

4.6

29.	Did the Permittee update and maintain an inventory, database, list, map, or other equivalent tracking system of private commercial and industrial sites that discharge stormwater pollutants to the MS4, per 4.6.B.1?		
	Yes	No	
	If no, please explain why	OPTIONAL):	
30.	The Permittee shall su attachment.	omit one (1) copy of their 4.6.B.1 Inventory as an	
	Please submit the Privattachment in MS Excel	ate Commercial and Industrial Inventory List as an or Adobe PDF.	
31.	31. Did the Permittee develop a mechanism to identify and document facilities subto the MSGP that did not file a timely NOI (does not apply to sites with waive and No Discharge Certificates) and contain a means of communication value operators of these facilities to inform them of their responsibility to comply, 4.6.B.2?		
	Yes	No	
	If no, please explain why	OPTIONAL):	
32.	•	all facilities identified in 4.6.B.1, per 4.6.C, once within (or approximately 20% each year)?	
	Yes	No	
	If no, please explain why	(OPTIONAL):	

33.	Is the Permittee implementing an effective compliance and enforcement program that incorporates escalating action for violations to municipal stormwater requirements, ordinance, or code, per 4.6.D?		
	Yes	No	
	If no, please explain why (OPT)	IONAL):	
Con	struction Sites		
34.	4. Did the Permittee provide new employee training at least one (1) time per year, per 4.7.A?		
	Yes	No	
	No new employees were hired during the reporting year.		
	If no, please explain why (OPTIONAL):		
	Did the Permittee provide refresher training for existing employees directly involved in these activities at least once every two (2) years, per 4.7.A?		
	Yes	No	
	If no, please explain why (OPTI	ONAL):	

4.7

35.	For construction projects that will result in land disturbance of one (1) acre or more (including those less than one (1) acre, but are part of a larger common plan of development), did the Permittee review at least 80% of plans for new development and redevelopment, per 4.7.B?		
	Yes	No	
	If no, please explain why (OPTION	NAL):	
36.	How many applications for new of acre or greater discharging to the	development and redevelopment projects one MS4 were reviewed, per 4.7.B?	
37.	Did the Permittee develop and up and municipal), per 4.7.C.1?	odate comprehensive inventories (e.g. private	
	Yes	No	
	If no, please explain why (OPTION	IAL):	
38.	to the CGP that did not file a time! No Discharge Certificates) and cor	anism to identify and document facilities subject by NOI (does not apply to sites with waivers or atain a means of communication with operators their responsibility to comply, per 4.7.C.2?	
	Yes	No	
	If no, please explain why (OPTION	IAL):	

39.	Did the Permittee inspect construction sites identified in the inventory in 4.7.C.1 at least one (1) time every three (3) months for highest priority sites and at least one (1) time every six (6) months for lowest priority sites, based on the prioritization schedule requirements, per 4.7.E.1?		
	Yes	No	
	If no, please explain why	OPTIONAL):	
40.	40. Did the Permittee conduct follow-up actions of construction sites to ensustormwater deficiencies/concerns/non-compliance identified as a result of routine inspection were corrected, per 4.7.E.2?		
	Yes	No	
	If no, please explain why	OPTIONAL):	
41.		e to require that plans include erosion and sedimentative of water quality, per 4.7.F?	ent
	Yes	No	
	If no, please explain why	OPTIONAL):	

4.8 Post-Construction

42.	Did the Permittee provide new employee training at least (1) one time per year to employees with direct stormwater responsibilities, per 4.8.A.1?		
	Yes N	0	
	No new employees were hire	d during the reporting year.	
	If no, please explain why (OPTIONAL):	
	Did the Permittee provide refreshe involved in these activities at least on	r training for existing employees directly ce every two (2) years, per 4.8.A?	
	Yes N	o	
	If no, please explain why (OPTIONAL):	
43.	areas of new development and rede	am to control stormwater discharges from evelopment after construction is complete, in BMPs, ordinances and policies, per	
	Yes N	0	
	If no, please explain why (OPTIONAL):	
44.	attach as part of your first year an	nitted prior to the first year annual report, nual report, the proposal and supporting erform the retrofit feasibility assessment.	

If applicable, attach the proposal for Retrofit sites as an attachment.

- 45. For the fourth year annual report, was a feasibility assessment developed to retrofit existing developed sites that are impacting water quality, per 4.8.B.3?Not applicable for this reporting year.
- 46. Attach, as part of your fourth year annual report, the 4.8.B.3 retrofit feasibility assessment.

Not applicable for this reporting year.

47. Did the Permittee inspect at least 90% of sites identified in 4.7.C.1 within one (1) year after construction completion to determine the compliance of their post-construction stormwater controls, per 4.8.C.2?

Yes No

If no, please explain why (OPTIONAL):

Certification

MS4 Certifier Name (printed):

I certify under penalty of law, that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gathered and evaluated the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

MS4 Certifier Signature:	Date
WISH CELLITE SIGNALUIE.	Date

Scottsdale Water 2023 Stormwater Annual Report Attachment B - Operation & Maintenance Expenditures

Program/Activity		FY 22/23 Actual
Construction Oversight		
Municipal & Private inspections	\$	57,466
Community Maintenance		_
IBW Maintenance	\$	30,734
Water Resources - Camel truck/staff		
Camel truck/staff, maintenance	\$	7,531
Water Quality		
-	\$	4,500
Operating expenses	•	111,274
Staff time (Inspections, IDDE, program oversight)	\$	123,754
ADEQ fee	\$	10,143
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	\$	249,671
City Attorney's Office	\$	90
Transportation/Street Operations		
MS4 Asset Maintenance	\$	48,475
Annual Total	\$	393,967

Scottsdale Water 2023 Stormwater Annual Report Attachment C - IDDE Summary

AZPD Perm	DES nit No.	Request ID	Date Reported	Date Resolved	Response Time (days)	WOTUS Impac	ct Address	Pollutant Source	Correction Method	Request Status
AZS0	00020	565907	Jul 5 2022 2:02PM	Jul 6 2022 9:30AM	:	1 N	No 104TH ST/MOUNTAIN VIEW	Pool Discharge	Site visit, education	Closed
	00020	566963	Jul 13 2022 12:08PM	Jul 14 2022 9:25AM	2	1 N	No 8730 E WELDON AV	Pool Discharge	Site visit, education	Closed
	00020	567640	Jul 18 2022 9:05PM	Jul 19 2022 9:34AM			No 3918 N 85TH ST	Pool Discharge	Site visit, education	Closed
			Jul 21 2022	Jul 21 2022						
	00020	568056	12:56PM Jul 22 2022	1:27PM Jul 25 2022	≤1		No 9312 N 94th Street	Pool Discharge	Site visit, education	Closed
AZS0	00020	568246	6:32PM Jul 27 2022	12:27PM Aug 1 2022	3	3 1	No 7730 E GOLD DUST AV	Pool Discharge	Site visit, education	Closed
AZS0	00020	568877	4:05PM Jul 29 2022	3:43PM Jul 29 2022	Š	5 N	No 8732 E MONTEBELLO AV	Pool Discharge	Site visit, education	Closed
AZS0	00020	569133	11:11AM Aug 2 2022	12:33PM Aug 3 2022	≤1	L N	No 10266 N 79TH ST	Pool Discharge	Site visit, education	Closed
AZS0	00020	569767	6:04PM Aug 3 2022	8:17AM Aug 4 2022	1	1 N	No 7773 E VIA DE DELLEZA	Pool Discharge	Site visit, education	Closed
AZS0	00020	569797	7:58AM	7:34AM	1	1 N	No 8014 E DEL JOYA DR	Stormwater Quality	Site visit, education	Closed
AZS0	00020	570144	Aug 5 2022 9:12AM	Aug 5 2022 11:33AM	≤1	L N	No 8576 E Sharon Dr	Pool Discharge	Site visit, educated pool company	Closed
AZS0	00020	570850	Aug 11 2022 4:04AM	Aug 11 2022 9:51AM	≤1	L N	No 8706 N 80TH PL	Pool Discharge	Site visit, education	Closed
AZS0	00020	571042	Aug 12 2022 9:14AM	Aug 12 2022 12:31PM	≤1	ı N	No 9689 E. TOPAZ DR.	Pool Discharge	Site visit, education	Closed
AZS0	00020	572848	Aug 23 2022 4:05PM	Aug 24 2022 8:43AM	:	1 N	No 6908 E VIRGINIA	Pool Discharge	Site visit, education	Closed
AZS0	00020	573278	Aug 26 2022 12:32PM	Aug 29 2022 12:33PM	3	3 1	No 7824 N VIA DEL MUNDO	Pool Discharge	Site visit, education	Closed
	00020	573508	Aug 29 2022 8:09AM	Aug 29 2022 12:35PM	≤1		No 8150 E VISTA DR	Pool Discharge	Site visit, education	Closed
	00020	573931	Aug 31 2022 10:58AM	Sep 1 2022 12:43PM			No 6707 N 82ND PL	Pool Discharge	Site visit, education	Closed
			Sep 1 2022	Sep 1 2022				_		
	00020	574151	8:39AM Sep 5 2022	12:41PM Sep 6 2022	≤1		No 10660 E CLINTON ST	Pool Discharge	Site visit, education	Closed
AZS0	00020	574669	9:51PM Sep 12 2022	12:38PM Sep 14 2022	1	1 N	No 7818 N VIA DE LAS BRISAS	Pool Discharge	PD stopped discharge	Closed
AZS0	00020	575773	2:17PM Sep 13 2022	6:48AM Sep 13 2022	2	2 N	No 8838 E LUPINE AV	Pool Discharge	Site visit, education	Closed
AZS0	00020	575897	9:28AM Sep 13 2022	12:56PM Oct 10 2022	≤1	1 N	No 9736 E TURQUOISE AVE	Pool Discharge	Site visit, education	Closed
AZS0	00020	575948	10:51AM Sep 16 2022	10:28AM Sep 19 2022	27	7 N	No 9736 E TURQUOISE AVE.	Pool Discharge	No action; call taker duplicated request	Closed
AZS0	00020	576757	3:48PM Sep 17 2022	9:08AM Sep 19 2022	3	3 N	No 8030 N Via De Lago	Pool Discharge	Site visit, education	Closed
AZS0	00020	577012	5:34PM	1:08PM	2	2 N	No 4925 N SCOTTSDALE RD	Pool Discharge	Site visit, education	Closed
AZS0	00020	577129	Sep 19 2022 8:15AM	Sep 19 2022 9:07AM	≤1	ı M	No 8149 E CRESTWOOD WY	Pool Discharge	Site visit, education	Closed
AZS0	00020	577729	Sep 21 2022 11:48AM	Sep 21 2022 1:59PM	≤1	L N	No 9319 E DESERT TR	Pool Discharge	Irrigation leak; no action taken	Closed
AZS0	00020	577805	Sep 21 2022 3:04PM	Sep 22 2022 1:06PM	:	1 N	No 10117 N 92ND ST BLDG B STE 101	Stormwater Quality	Site visit, education. Revisited to ensure proper clean up.	Closed
AZS0	00020	578615	Sep 26 2022 8:53AM	Sep 26 2022 10:17AM	≤1	ı N	No 7407 E TURQUOISE AV	Pool Discharge	Site visit, education	Closed
AZS0	00020	579770	Sep 30 2022 10:23PM	Oct 3 2022 11:30AM	3	3 1	No 4160 N CRAFTSMAN CT	Stormwater Quality	Site visit, determined to be irrigation break.	Closed
	00020	580535	Oct 4 2022 11:17AM	Oct 4 2022 1:19PM	≤1	ı N	No 6504 E OBERLIN WAY	Pool Discharge	Site visit, education	Closed
	00020	580683	Oct 4 2022 6:43PM	Oct 5 2022 12:27PM			No 10881 N 120TH ST	Pool Discharge	Site visit, education	Closed
	00020		Oct 7 2022 1:00PM	Oct 12 2022				_		
		581353	Oct 10 2022	6:09AM Oct 10 2022			NO 11448 N MILLER RD	Pool Discharge	Site visit, education	Closed
AZS0	00020	581797	11:00AM Oct 13 2022	12:37PM Oct 13 2022	≤1	1 N	No 8919 E CALLE DEL PALO VERDE	Pool Discharge	Site visit, education	Closed
AZS0	00020	582605	8:14AM Oct 20 2022	12:34PM Oct 20 2022	≤1	L N	No 9300 E GRAPVINE PASS	Pool Discharge	Site visit, education	Closed
AZS0	00020	583910	11:08AM Oct 20 2022	11:49AM Oct 21 2022	≤1	1 N	No 8205 E DEL CADENA DR	Pool Discharge	Site visit, education Site visit. Residential car washing is permitted.	Closed
AZS0	00020	584015	6:47PM Oct 27 2022	10:28AM Oct 27 2022	i	1 N	No 8224 E THOROUGHBRED TR	Stormwater Quality	Discussed BMPs with resident.	Closed
AZS0	00020	585693	8:23AM Nov 1 2022	10:22AM Nov 2 2022	≤1	ı N	No 13718 N 89TH WY	Pool Discharge	Site visit, education	Closed
AZS0	00020	587079	10:34AM	9:01AM	1	1 N	No 11416 N 86TH ST	Pool Discharge	Site visit, education	Closed
AZS0	00020	587822	Nov 3 2022 4:29PM	Nov 4 2022 8:26AM	į	1 N	No 11389 N 122ND ST	Pool Discharge	Site visit, education	Closed
AZS0	00020	587843	Nov 3 2022 7:03PM	Nov 4 2022 8:24AM	1	1 N	No 11389 N 122ND ST	Pool Discharge	No action taken; duplicate	Closed
AZS0	00020	587853	Nov 3 2022 7:18PM	Nov 4 2022 1:36PM	:	1 N	No 11389 N 122ND ST	Pool Discharge	No action taken; duplicate	Closed
AZS0	00020	587956	Nov 4 2022 11:56AM	Nov 4 2022 12:23PM	≤1	L N	No 10829 N 83RD ST	Pool Discharge	Site visit, education	Closed
AZS0	00020	590408	Nov 15 2022 2:48PM	Nov 16 2022 2:34PM	1	L N	No 15345 N SCOTTSDALE RD STE 100	Pool Discharge	Site visit, education	Closed

AZS000020	590640	Nov 16 2022 12:27PM	Nov 16 2022 1:37PM	≤1	No 8508 E SWEETWATER BLVD	Pool Discharge	Site visit, education Unable to confirm claim of illegal discharge. Left	Closed
AZS000020	592186	Nov 23 2022 11:28AM	Jan 3 2023 6:25AM Nov 30 2022	42	No 8260 E RAINTREE DR	Stormwater Quality	request open while staff monitored site routinely for several weeks.	Closed
AZS000020	593142	Nov 29 2022 3:17PM	8:44AM	1	No 17805 N 97TH PL	Pool Discharge	Site visit, education	Closed
							Site visit and BMP education. Instructed manager to	
475000000	F02070	Dec 2 2022	Dec 2 2022		N- 45444 N HAVDEN DD CTC 470	Improper waste	inspect area regularly, properly clean area and use	Cl1
AZS000020	593870	9:33AM Dec 4 2022	1:34PM Dec 5 2022	≤1	No 15111 N HAYDEN RD STE 170	disposal	absorbent material for future spills.	Closed
AZS000020	594408	8:01PM Dec 6 2022	10:23AM Dec 6 2022	1	No 5818 N 83RD PL	Pool Discharge	Site visit, education	Closed
AZS000020	594703	7:18AM	9:21AM	≤1	No 8502 E INDIANOLA AV.	Pool Discharge	Site visit, education	Closed
AZS000020	595684	Dec 8 2022 2:21PM	Dec 9 2022 10:25AM	1	No Via De Ventura / Via Linda	Pool Discharge	Site visit, education	Closed
AZS000020	596876	Dec 14 2022 9:46AM	Dec 15 2022 6:02AM	1	No 8317 E VIA DE DORADO	Pool Discharge	Site visit, education	Closed
							Site visits, monitoring. Hauling company initiated environmental cleanup effort before our arrival. OEI	
AZS000020	596895	Dec 14 2022 10:35AM	Dec 14 2022 10:57AM	≤1	No 4408 N MILLER RD	Accidental spill	follow up, manhole monitoring to ensure residual fuel properly remediated.	Closed
		Dec 15 2022	Dec 16 2022					
AZS000020	597161	1:25PM Dec 15 2022	10:35AM Dec 16 2022	1	No 8631 N FARVIEW DR	Pool Discharge	Site visit, education	Closed
AZS000020	597170	1:43PM Dec 15 2022	10:29AM Dec 16 2022	1	No 8631 N FARVIEW DR	Pool Discharge	Site visit, education	Closed
AZS000020	597172	1:46PM	10:34AM	1	No 8649 N FARVIEW DR	Pool Discharge	No action taken; duplicate	Closed
AZS000020	597192	Dec 15 2022 2:37PM	Dec 16 2022 12:00PM	1	No 8649 N FARVIEW DR	Pool Discharge	No action taken; duplicate	Closed
AZS000020	598774	Dec 23 2022 11:57AM	Dec 23 2022 1:10PM	≤1	No 9288 E HILLERY WY	Pool Discharge	Site visit, education	Closed
AZS000020	598780	Dec 23 2022 12:21PM	Dec 27 2022 2:43PM	4	No 8156 E COLUMBUS AV	Pool Discharge	Site visit, education	Closed
		Jan 3 2023	Jan 4 2023			Pool Discharge		
AZS000020	600681	5:36PM Jan 5 2023	11:49AM Jan 5 2023	1	No 8214 E LINCOLN DR	· ·	Site visit, education	Closed
AZS000020	601194	1:47PM Jan 6 2023	2:58PM Jan 6 2023	≤1	No 8520 E ROSE LN	Pool Discharge	Site visit, education	Closed
AZS000020	601446	1:01PM Jan 9 2023	2:04PM Jan 9 2023	≤1	No 8976 E FRIESS DR	Pool Discharge	Site visit, education	Closed
AZS000020	601999	10:39AM Jan 9 2023	12:23PM Jan 10 2023	≤1	No 6302 N 87TH STREET	Pool Discharge	Site visit, education	Closed
AZS000020	602202	7:04PM Jan 9 2023	9:39AM Jan 10 2023	1	No 6443 E SHERIDAN ST	Pool Discharge	Site visit, education	Closed
AZS000020	602208	7:34PM	9:40AM	1	No 6402 E VERNON AV	Pool Discharge	Site visit, education	Closed
AZS000020	602325	Jan 10 2023 10:51AM	Jan 10 2023 2:52PM	≤1	No 8948 E DAHILIA DR	Pool Discharge	Site visit, education	Closed
AZS000020	602596	Jan 11 2023 9:36AM	Jan 11 2023 12:59PM	≤1	No 8314 E CLARENDON AVE	Pool Discharge	Site visit, education	Closed
AZS000020	603524	Jan 14 2023 7:01PM	Jan 17 2023 10:38AM	3	No 7752 N VIA DE LA MONTANA	Pool Discharge	Site visit, education	Closed
AZS000020	604054	Jan 18 2023 9:26AM	Jan 18 2023 2:24PM	≤1	No 908 N 72ND PL	Pool Discharge	Site visit, education	Closed
AZS000020	606687	Feb 1 2023 12:56PM	Apr 3 2023 5:58AM	62	No 7526 E COOLIDGE ST	Pool Discharge	No action; call taker didn't save request properly	Closed
A7S000020	607453	Feb 7 2023 7:18AM	Feb 7 2023 1:25PM	<1	No 8723 E VIA TAZ SUR	Pool Discharge	Site visit, education	Closed
A23000020	007433			21	NO 0723 E VIA TAZ SON	1 ooi Discharge	Site visit, instructed to monitor trash enclosure and	ciosca
AZS000020	607925	Feb 10 2023 10:21AM	Feb 10 2023 1:24PM	≤1	No 20581 N HAYDEN RD	Illegal dumping	rendering bin regularly. BMPs on spill prevention/management.	Closed
AZS000020	608350	Feb 14 2023 11:28AM	Feb 14 2023 2:35PM	≤1	No 7601 E INDIAN BEND RD	Pool Discharge	Site visit, education	Closed
AZS000020	608920	Feb 18 2023 10:30AM	Feb 21 2023 12:45PM	3	No 8330 E CHERYL DR	Pool Discharge	Site visit, education	Closed
AZS000020	609820	Feb 24 2023 12:18PM	Feb 24 2023 2:00PM	≤1	No 7735 E Hartford Dr	Pool Discharge	Site visit, education	Closed
AZS000020	610737	Mar 2 2023 10:40AM	Mar 2 2023 1:11PM	≤1	No 8102 E WINDSOR AV	Pool Discharge	Site visit, education	Closed
		Mar 3 2023	Mar 3 2023			_	•	
AZS000020	610906	11:50AM Mar 3 2023	1:45PM Mar 3 2023	≤1	No 7517 E WOODSAGE LN	Pool Discharge	Site visit, education	Closed
AZS000020	610912	12:05PM Mar 7 2023	1:47PM Apr 28 2023	≤1	No 8556 N WOODLAND CT	Pool Discharge	Site visit, education	Closed
AZS000020	611361	11:29AM Mar 9 2023	2:36PM Mar 9 2023	53	No 10380 E CORRINE DR	Pool Discharge	No action; call taker didn't save request properly Site visit, instructed homeowner to clean spill. BMPs	Closed
AZS000020	611755	12:43PM Mar 13 2023	2:18PM Mar 13 2023	≤1	No 8336 N 72ND PL	Illegal dumping	on spill prevention	Closed
AZS000020	612239	1:16PM	2:45PM	≤1	No 8819 N 85TH CT	Pool Discharge	Site visit, education	Closed
AZS000020	612402	Mar 14 2023 12:58PM	Mar 15 2023 8:29AM	1	No 4726 N 83RD ST	Pool Discharge	Site visit, education	Closed
AZS000020	613218	Mar 20 2023 7:28PM	Mar 21 2023 9:42AM	1	No 6908 E CHEERY LYNN RD	Pool Discharge	Site visit, education	Closed
AZS000020	614077	Mar 27 2023 3:12PM	Mar 28 2023 12:49PM	1	No 10542 N 110TH PL	Pool Discharge	Site visit, education	Closed
AZS000020	614784	Mar 31 2023 4:18PM	Apr 3 2023 12:33PM	3	No 6619 E 6TH ST	Pool Discharge	Site visit, education	Closed
AZS000020	615731	Apr 6 2023 11:03AM	Apr 6 2023 1:03PM	≤1	No 12242 N 74TH ST	Pool Discharge	Site visit, education	Closed
			-	-	-		***************************************	

A	ZS000020	615996	Apr 8 2023 1:10PM	Apr 10 2023 9:35AM	2	No 8584 E VIA DE DORADO	Pool Discharge	Site visit, education	Closed
Λ.	ZS000020	616059	Apr 9 2023 7:30PM	Apr 10 2023 9:37AM	1	No E SHEA BL/N 68TH ST	Pool Discharge	Site visit, education	Closed
^	23000020		Apr 12 2023	Apr 12 2023	-		_		
A	ZS000020	616422	7:34AM Apr 13 2023	10:54AM Apr 14 2023	≤1	No 8620 E CORTEZ ST	Pool Discharge	Site visit, education	Closed
A	ZS000020	616738	5:29PM	9:36AM	1	No 9227 E HILLERY WY	Pool Discharge	Site visit, education	Closed
A	ZS000020	617726	Apr 20 2023 5:04PM	Apr 21 2023 11:34AM	1	No 8047 E MICHELLE DR	Pool Discharge	Site visit, education	Closed
Δ	ZS000020	618207	Apr 25 2023 8:57AM	Apr 25 2023 1:40PM	≤1	No 8117 E GLENROSA AV UNIT 198	Improper waste disposal	Site visit, instructed to clean spill. BMPs on spill prevention	Closed
			Apr 25 2023	Apr 26 2023					
A.	ZS000020	618339	3:36PM Apr 28 2023	11:17AM May 1 2023	1	No 13439 N 79TH ST	Pool Discharge	Site visit, education	Closed
A	ZS000020	618878	10:51PM May 3 2023	9:22AM May 3 2023	3	No 14879 N 93RD WY	Pool Discharge	Site visit, education	Closed
A	ZS000020	619646	9:45AM	12:10PM	≤1	No 10359 N 98TH ST	Pool Discharge	Site visit, education	Closed
A	ZS000020	619775	May 4 2023 8:35AM	May 4 2023 10:05AM	≤1	No 9711 E PERSHING AV	Pool Discharge	Site visit, education	Closed
Λ.	ZS000020	619870	May 4 2023 3:28PM	May 5 2023 12:22PM	1	No 8701 E VERNON AV	Pool Discharge	Site visit, education	Closed
A	23000020		May 5 2023	Jul 14 2023			_		
A	ZS000020	619900	7:03AM May 9 2023	1:00PM May 9 2023	71	No 2311 N MILLER RD	Pool Discharge	No action; call taker didn't save request properly	Closed
A	ZS000020	620359	12:49PM	1:06PM	≤1	No 6844 E BELLEVIEW	Pool Discharge	Site visit, education	Closed
A	ZS000020	620419	May 9 2023 7:01PM	May 10 2023 9:57AM	1	No 7492 E TIMERLANE CT	Pool Discharge	Site visit, education	Closed
A	ZS000020	620677	May 12 2023 7:51AM	May 12 2023 7:55AM	≤1	No 907 N 73RD PL	Pool Discharge	Site visit, education	Closed
	ZS000020	621217	May 17 2023 7:37AM	May 17 2023 9:42AM		No 8580 E VIA DE RISA	Pool Discharge	Site visit, education	Closed
A	23000020	621217	May 31 2023	Jun 1 2023	≤1	NO 8380 E VIA DE RISA	Pool Discharge	Site visit, education	Closed
A	ZS000020	622900	12:59PM May 31 2023	7:34AM May 31 2023	1	No 8638 E VALLEY VIEW DR	Pool Discharge	Site visit, education	Closed
A	ZS000020	622903	1:17PM	1:20PM	≤1	No 8638 E VALLEY VIEW DR	Pool Discharge	No action taken; duplicate	Closed
A	ZS000020	623166	Jun 2 2023 10:53AM	Jun 5 2023 5:42AM	3	No 9018 E ALTADENA ST	Pool Discharge	Site visit, education	Closed
A	ZS000020	623519	Jun 6 2023 10:15AM	Jun 6 2023 2:58PM	≤1	No 9025E JENAN DR	Pool Discharge	Site visit, education	Closed
			Jun 6 2023	Jun 6 2023		N- 7040 NIVIA DE LAS RRISAS	_		Cl1
A	ZS000020	623554	12:43PM Jun 9 2023	1:05PM Jun 12 2023	≤1	No 7818 N VIA DE LAS BRISAS	Pool Discharge	Site visit, education	Closed
A	ZS000020	624953	2:14PM Jun 13 2023	2:04PM Jun 13 2023	3	No 8235 E CAMBRIDGE AV	Pool Discharge	Site visit, education	Closed
A	ZS000020	625225	6:38AM	6:51AM	≤1	No 7520 E MCKINLEY ST	Pool Discharge	Site visit, education	Closed
A	ZS000020	625270	Jun 13 2023 10:15AM	Jun 13 2023 12:58PM	≤1	No 2107 N 68TH PL	Pool Discharge	Site visit, education	Closed
A	ZS000020	625385	Jun 14 2023 8:40AM	Jun 14 2023 9:06AM	≤1	No 3614 N 68TH ST	Pool Discharge	Site visit, education	Closed
			Jun 16 2023	Jun 16 2023			_		
A.	ZS000020	625731	11:19AM Jun 17 2023	11:24AM Jun 20 2023	≤1	No 27818 N 111TH ST	Pool Discharge	Site visit, education	Closed
A	ZS000020	625806	5:12PM Jun 17 2023	1:08PM Jun 21 2023	3	No 22087 N 77TH ST	Pool Discharge	Site visit, education	Closed
A	ZS000020	625807	5:33PM	10:49AM	4	No 22495 N 77TH ST	Pool Discharge	Site visit, education	Closed
A	ZS000020	625829	Jun 18 2023 9:59AM	Jun 20 2023 9:00AM	2	No 6302 N 87TH ST	Pool Discharge	Site visit, education	Closed
Δ	ZS000020	625922	Jun 19 2023 5:51PM	Jun 20 2023 9:40AM	1	No 10635 N 99TH ST	Pool Discharge	Site visit, education	Closed
			Jun 19 2023	Jun 20 2023					
A	ZS000020	625929	7:15PM Jun 20 2023	7:40AM Jun 20 2023	1	No 10635 N 99TH ST	Pool Discharge	Site visit, education	Closed
A	ZS000020	626035	10:59AM Jun 22 2023	11:47AM Jun 23 2023	≤1	No 9025 E JENAN DR	Pool Discharge	Site visit, education	Closed
A	ZS000020	626376	2:54PM	11:14AM	1	No 11387 E CARIBBEAN LN	Pool Discharge	Site visit, education	Closed
A	ZS000020	568111	Jul 21 2022 4:07PM	Jul 22 2022 1:03PM	1	No 8538 E VALLEY VISTA DR	Pool Discharge	Site visit, education	Closed

Scottsdale Water Municipal Facility Inventory

		Mamorpai i ac	ty		y										
Building Name	Address 1	Site Code		Water Site	Fire & Police Stations		Parks & Trailheads	Parks Maintenance	Equipment storage and maintenance	Fleet maintenance	Hazardouse waste disposal	materials/waste storage yards/processing	POTWs and sludge handling areas	street repair & maintenance yards	other reason for significant pollutant source
Arsenic Treatment Facility-32	11606 N 64th St	COS	Χ	_	_ ,,		_	_		_		- " ~		" -	0 0, =
Cactus Park Pool	7202 E Cactus Rd	SCOTTSDALE				Χ	X								
CAP 1 (canal intake)	16800 N. Hayden Rd	WATER	Χ												
CAP Plant	8660 E Union Hills Dr	WATER	Χ												
Central Groundwater Treatment Facility - Pima	8600 E Thomas Rd	WATER	Χ												
Chaparral Park & Pool	5401 N Hayden Rd	CHAP PRK				Χ	Х								
Chaparral Water Treatment Plant CWTP	8111 E. McDonald Dr	WATER	Χ												
Copper Ridge Park Maintenance/Restroom	10101 E Thompson Peak Pa	COPPER RIDGE PR	K			Χ	X								
Eldorado Park & Pool	2311 N Miller Rd	ELDO PRK				Χ	X								
Fire Station 601	1901 N Miller Rd	FIRE STATIONS			X										
Fire Station 602	7522 E Indian School Rd	FIRE STATIONS			X										
Fire Station 603	8191 E Indian Bend Road	FIRE STATIONS			X										
Fire Station 604	9045 E Via Linda	FIRE STATIONS			X										
Fire Station 605	7455 E Shea Rd	FIRE STATIONS			X										
Fire Station 606	10850 E Via Linda	FIRE STATIONS			X										
Fire Station 607	11230 N 132nd St	FIRE STATIONS			X										
Fire Station 608	9598 E Cactus Rd	FIRE STATIONS			X										
Fire Station 609	14970 N 78th Way	FIRE STATIONS			X										
Fire Station 610	16701 N 100th St	FIRE STATIONS			X X										
Fire Station 611 Fire Station 613	20355 N Pima Rd 26380 N Hayden Rd	FIRE STATIONS FIRE STATIONS			X										
Fire Station 613	27775 N. Alma School Pkwy				^ X										
Fire Station 615	31802 N Pima Rd	FIRE STATIONS			X										
Fire Station 616	10905 E Loving Tree Lane	FIRE STATIONS			X										
Gainey Ranch WWTP	7283 E Mountain View Rd	WATER	Х												
Groundwater Treatment Facility NGTF	5985 N. Cattle Track Dr	WATER	Χ												
Horizon Park	15444 N 100th St	HORIZON PRK				Χ	X								
Indian School Park	4289 N Hayden Rd	ISP PRK				Χ	Χ								
McCormick Railroad Park Maintenance Compound		MCCORMICK PRK				Χ	X								
McDowell Mountain Ranch Park	10203 E McDowell Mtn Ranc	MMR PRK				Χ	X								
McKellips Park	7701 E McKinley St.	MCKELLIPS PRK				Χ	Х								
Mountain View Park	8625 E Mountain View Rd	MTN VIEW PRK				Χ	Χ								
North Corporation Yard	9191 E San Salvador Dr	NCY)	X	X		X	,	Κ	
Northeast Pumpback	13053 N 87th St	PUMP STATION	Х												
Northwest Pumpback	7535 E Redfield Rd	PUMP STATION	Х		.,										
Police Department Horse Barn (WESTWORLD)	16600 N Pima Rd	POLICE DEPT	.,		X										
S-100		WATER	X												
S-102 S-103		WATER WATER	X												
S-103 S-105		WATER	X												
S-114		WATER													
S-114 S-115		WATER	X												
S-120		WATER	X												
S-124		WATER	X												
S-126		WATER	X												
			, ·												

S-143		WATER	Χ							
S-145		WATER	X							
S-146		WATER	X							
S-147		WATER	X							
S-179		WATER	X							
S-32		WATER	Χ							
S-36-3		WATER	Χ							
S-36-5		WATER	X							
S-41		WATER	X							
S-42		WATER	X							
S-43		WATER	X							
S-50		WATER	X							
S-53		WATER	X							
S-54		WATER	X							
S-55		WATER	X							
S-57		WATER	X							
S-65		WATER	X							
S-79		WATER	X							
S-80		WATER	X							
S-83		WATER	X							
S-85		WATER	Χ							
S-90		WATER	Χ							
S-92B		WATER	X							
S-93		WATER	Χ							
S-94		WATER	X							
Scottsdale Ranch Park	10400 E Via Linda	SRP PRK		Χ	Χ					
SIS Bowtie	15636 N 78th St	SIS BOWTIE								
Solid Waste Transfer Station	8417 E. Union Hills Dr	TRANSFER STATION	١							SOLID WASTE
South Corporation Yard Complex	7601 E McKellips Rd	SOUTH CORP YARD)			Χ	Χ	X	X	
Southeast Pumpback	8815 E Via Linda	PUMP STATION	Χ							
Southwest Pumpback	7301 E. Doubletree Ranch	PUMP STATION	Χ							
Stadium & Baseball Maintenance (center field)	7408 E Osborn Rd	STADIUM			X					
Thomas Groundwater Treatment Facility TGTF	8650 E. Thomas Road	WATER	X							
Thompson Peak Park	20199 N. 78th Pl	THOMPSON PK PRK	, L	Χ	Χ					
Troon Reclamation	24301 N. Alma School Rd	COS	X							
Water Campus-reclamation and AWT	8787 E Hualapai Dr	WATER	X							
Water Site 42 - Jomax	26602 N Pima Rd	JOMAX	X							
WestWorld	16601 N Pima Rd	WESTWORLD								Χ

shaded cells indicate high-priority site
*Updated January 2023